



BLACK DIAMOND RECON LT AVALANCHE TRANSCEIVER RECALL

Black Diamond Equipment®, in conjunction with the U.S. Consumer Product Safety Commission (CPSC) and Health Canada, is recalling the Black Diamond Recon LT avalanche transceiver and related avalanche safety sets.

In some cases, the metal contact of the Recon LT's switch mechanism may corrode. If this occurs, the device could malfunction or turn off, potentially hindering avalanche rescue efforts and increasing the risk of serious injury or death. Consumers who own the Black Diamond Recon LT should immediately stop using it and follow the recall procedures.

To date, Black Diamond has received six consumer reports related to this issue, with no injuries, accidents, or fatalities.

Black Diamond is committed to addressing this matter swiftly and proactively. Recon LT owners can have their transceiver repaired, exchanged for a different model, or refunded.

Affected Products:

This recall affects all Black Diamond Recon LT transceivers manufactured and sold between June 1, 2021 and February 14, 2025, with serial numbers starting with the range 2040—2321. The serial number can be found by connecting your transceiver to the PIEPS app via Bluetooth. This transceiver was sold as a standalone unit and as part of Alpine Avy Safety Sets and Recon Avy Safety Sets.



Customers who own a Recon LT should immediately stop using it and contact Black Diamond to initiate the recall process

