



P.O. Box 143  
Moran, TX 76464  
Office 325-762-6551

December 3, 2024

Thank you for purchasing the SSAR-15 MOD. It is with our deepest apologies that we request the return of your purchased product temporarily. There is a chance your stock is not affected, however, to avoid disappointment with the product use we ask that it be returned for a quick inspection and correction if necessary.

The SSAR-15 MOD is our most distinguished model in the AR-15 line up and as such it has multiple options and functions. The stock is equipped with a Cam Roller Pin that increases the tolerance of the stock at the buffer tube during non-bump fire operation for precision type shooting. We have found that there is a moderate quantity of stocks where the Cam Block, lifted by the Cam Roller Pin was installed backwards. There are no safety concerns, only that the tolerances of the Cam Block require it to be installed in a single direction otherwise the buffer tube may not move as freely as required and could interrupt the bump fire operation. This is a non-invasive repair that only takes minutes to accomplish, however we ask that you allow SLIDE FIRE conduct the inspection and correction if necessary so we can ensure proper fitment and operation.

Questions and concerns can be submitted to [customerservice@slidefire.com](mailto:customerservice@slidefire.com)

v/r

Tommy Cooksey  
Chief Operating Officer  
Slide Fire Solutions