



BLACK DIAMOND VISION HARNESS RECALL

(February 27, 2025) Black Diamond Equipment® is recalling the Vision harness due to premature degradation of its specialized materials and construction. This has the potential to create a risk of serious injury or death. Consumers who own the Black Diamond Vision harness should immediately stop using it and follow the recall procedures.

To date, Black Diamond has received one incident report involving a heavily used product in which the waist belt failed in an atypical manner with no injuries or fatalities. While the root cause is still under investigation, Black Diamond is recalling all the units out of an abundance of caution.

Black Diamond is committed to addressing this matter swiftly and proactively. Vision harness owners will have the option of a single use \$200.00 credit on blackdiamondequipment.com or Black Diamond retail store or a full refund in exchange for their recalled harness.

The U.S. Consumer Product Safety Commission (CPSC) and Health Canada have been notified.

Affected Products:

This recall applies to Black Diamond Vision harnesses (all sizes) manufactured and sold between January 1, 2018 and February 27, 2025.

This recall does not include the Vision AirNET RECCO or any other Black Diamond harness.



Customers who own a Vision harness should immediately stop using it and contact Black Diamond to initiate the recall process

